



www.BeSoji.com



PRE-PURCHASE YELLOW BOOK

BESOJI FZ-LLC

IN5 TECH, MEDIA CITY

+971 56 817 8171

HELLO@BESOJI.COM



Type Of Inspection

Accident History Inspection

Date
Wednesday, November 6, 2024

Time
11:00 AM

Vehicle Details

Make BMW	Model X2	Year 2018
Engine Size 4-Cylinder	Mileage (KM) 65888	Fuel Type Petrol
Regional Specs American	Transmission Automatic	Interior Leather
VIN Number 12345678998745612	Number of Keys 1	Spare Tire Not Available

Vehicle Summary

We've explained **some** of the faults below.
Please refer to the full report for all the faults.

Chassis/Subframe Damage

- **IMPORTANT:** Chassis damage found. Chassis damage refers to structural harm to the frame or underbody of a vehicle, compromising its integrity and safety. Repair costs for chassis damage can vary significantly. A vehicle is not guaranteed to pass Government Inspection if the chassis was damaged or repaired.

Repair cost ranges are general and not final. We offer these estimates to provide you more clarity on deciding if you should buy the car or not. These estimates may vary depending on the vehicle make and model, current labor rates, time period issue is present and the complexity of the repair.

Roof Lining

Dirty

Rear View Mirror

Pass

Armrest & Side Pockets

Pass

Steering Wheel Upholstery

Pass

Seats Upholstery

Pass

Gear Lever

Pass

Floor Mats

Pass

Trunk Lining

Pass

Dashboard

Pass

Front Windscreen

Pass

Rear Windscreen

Pass

Doors

Pass

Service History

Not Available

User Manual

Available

Roof Lining Fault




IMG_20240525_152810.jpg



IMG_20240525_152821.jpg

Service History & Manuals

Paint Condition Report




Key Details

- **Scratch:** A minor or major scratch
- **Paint Chip:** A small to medium part of the paint has been removed
- **Dent:** A minor or major depression or hollow on the vehicle body
- **Accident Paint:** Filler used to smoothen out the panel due to a deep crack or damage, followed by repainting of the panel.
- **Cosmetic Paint:** No filler used, usually a repaint due to minor imperfections on the paint. e.g. stone chips, door dings, etc.
- **Faded:** Paint and/or lacquer has been worn out due to extreme weather. Appears as a dull, washed out appearance and, at times discoloration.



Chassis, Subframe & Internal Damage Report



Damage on Chassis / Subframe:

Repaired

1

4

6

7

Chassis/Subframe Damage

• **IMPORTANT:** Chassis damage found. Chassis damage refers to structural harm to the frame or underbody of a vehicle, compromising its integrity and safety. Repair costs for chassis damage can vary significantly. A vehicle is not guaranteed to pass Government Inspection if the chassis was damaged or repaired.

Photos Of Chassis/Subframe Damage





Historical Photos Found



[bmw-x2-xdrive2-2018-wbxvj5c31jef82347-img1.jpg](#)



[bmw-x2-xdrive2-2018-wbxyj5c31jef82347-img2.jpg](#)



[bmw-x2-xdrive2-2018-wbxyj5c31jef82347-img3.jpg](#)



[bmw-x2-xdrive2-2018-wbxyj5c31jef82347-img4.jpg](#)



[bmw-x2-xdrive2-2018-wbxyj5c31jef82347-img5.jpg](#)



[bmw-x2-xdrive2-2018-wbxyj5c31jef82347-img7.jpg](#)



[bmw-x2-xdrive2-2018-wbxyj5c31jef82347-img8.jpg](#)

General Exterior Photos



Sample.jpeg
492.42 KB



sample (2).jpeg
465.47 KB



sample (3).jpeg
543.58 KB

Interior Photos



IMG_20240525_1524...
522.39 KB



IMG_20240525_1525...
491.66 KB



IMG_20240525_1525...
569.92 KB



IMG_20240525_1525...
533.52 KB



IMG_20240525_1525...
536.72 KB



IMG_20240525_1525...
456.5 KB



IMG_20240525_1525...
530.56 KB



IMG_20240525_1525...
506.87 KB



IMG_20240525_1525...
604.15 KB



IMG_20240525_1525...
540.15 KB



IMG_20240525_1526...
441.7 KB



IMG_20240525_1526...
502.7 KB



IMG_20240525_1526...
518.63 KB



IMG_20240525_1526...
479.96 KB



IMG_20240525_1526...
487.53 KB



IMG_20240525_1526...
517.37 KB



IMG_20240525_1526...
506.76 KB



IMG_20240525_1526...
468.71 KB



IMG_20240525_1527...
491.31 KB



IMG_20240525_1527...
495.9 KB



IMG_20240525_1527...
535.52 KB



IMG_20240525_1528...
456.73 KB



IMG_20240525_1528...
486.07 KB



IMG_20240525_1528...
477.3 KB



IMG_20240525_1528...
496.11 KB



WE JUST OUTPERFORMED YOUR INSURANCE BROKER

We've built the insurance experience from the ground up!

- Get Car Insurance Without Talking To A Human - For The First Time Ever!
- Lowest quotes, transparent pricing, instant cover available 24/7. Policy issued to RTA in 3 minutes.

TRY THE MAGIC



Terms of Service

All services from BeSoji are provided on an "as is, with all defects" and "as available" basis without warranties of any kind, either expressed or implied, including without limitation, warranties of title, non-infringement, or implied warranties of merchantability or fitness for a particular purpose. Nothing in these terms or in any description of products or services in the services shall constitute a representation or warranty with respect to such products or services.

The inspection of the vehicle described in this report is external and we are unable to accept responsibility for failure to identify defects not present or apparent at the time of the inspection. Odometer readings may have been tampered with, although we report any signs that we notice of this happening during inspection. You acknowledge, by your use of the services, that such use is at your sole risk. In the event of dissatisfaction or a complaint, we reserve the right to re-examine the vehicle prior to any rectifications to the vehicle. You agree that BeSoji's liability is limited to refunding the price you pay for the inspection in the event you are dissatisfied with BeSoji's service, or injuries occur due to an unreported defect in the vehicle. All requests should be sent to hello@besoji.com within 7 days notice of receiving the report.

in no event shall either BeSoji or its affiliates or agents be liable for any direct, indirect, punitive, incidental, special or consequential damages arising out of or in any way connected with the use of the services, whether based on contract, tort, strict liability or otherwise, even if advised of the possibility of any such damages.